

KENTUCKY INDIVIDUAL BUILDING SURVEY FORM

(KHC 2014-1)

SHPO EVALUATION:
INDIVIDUALLY ELIGIBLE

COUNTY Gallatin

RESOURCE # GA-16

EVALUATION D / Eligible: individually

SHPO EVALUATION _____

DESTROYED _____

1. NAME OF RESOURCE (how determined):

2 / Historic atlas or map
Gex House

2. ADDRESS/LOCATION:

N. Side of U.S. 42

3. UTM REFERENCE:

Quad Name: Vevay North, IND-KY Date: 1992
Zone: 16 Method: C / Commonwealth Base Map
Easting: 673,760.958925 Northing: 4,292,471.926179

4. OWNER/ADDRESS:

5. FIELD RECORDER/AFFILIATION:

Danna Allen, ERM

6. DATE RECORDED: 12/20/2015

7. SPONSOR: Nucor Gallatin

8. INITIATION: 3 / Review & Compliance

9. OTHER DOCUMENTATION:

☒ Survey ☐ HABS/HAER
☐ KY Land ☐ Local Land
☐ NHL ☐ NR10. REPORT/NR REFERENCE: *Historic Architectural Assessment for the Nucor Steel - Gallatin Direct Reduced Iron (DRI) Conveyor System Gallatin County, Kentucky 2016*

11. ORIGINAL PRIMARY FUNCTION:

01: Residential - A: Single Dwelling

12. CURRENT PRIMARY FUNCTION:

02: Commercial - 3: Other

13. CONSTRUCTION DATE: Estimated 6: 1850-1874

Documented:

14. DATE OF MAJOR ADDITIONS/MODIFICATIONS (specify):

0: Undetermined

15. CONSTRUCTION METHOD AND MATERIAL:

Original/Primary: B0 / Brick
Subsequent/Secondary: _____

16. DIMENSIONS: Height: C: 2 Story

Width: 5B Depth: DP Acreage:

17. PLAN:

First: H / Central passage, double pile
Second: _____

18. STYLISTIC INFLUENCE:

First: 3:1: Greek Revival
Second: 4:2: Italianate

19. FOUNDATION:

Type: 0 / Unknown/NA
Material: 0 / Unknown/NA

20. PRIMARY WALL MATERIAL:

Original: E / Brick, common bond
Replacement: _____

21. ROOF CONFIGURATION AND COVERING:

Configuration: 1 / Hip
Covering: 7 / Standing seam metal

22. CONDITION:

G / Good-in good state of repair

23. MODIFICATION: 1 / Little or no alteration

24. ARCHITECT/BUILDER:

25. PHOTOGRAPH FILE: CD

26. WINDOWS: ☐ Original ☒ Replacement

Type: Wood Sash Sash Configuration: 1/1

27. OUTBUILDINGS: Yes Number and type: 3/domestic

28. PHOTO




29. COMMENTS/HISTORICAL INFORMATION: A two-story, common bond brick, center passage, five bay, mid-19th century Greek Revival house with a stone water table, stone lintels and sills, brick pilasters on the façade, a standing seam metal hipped roof, four brick end chimneys, and a bracketed entry portico. There is a one-story, common bond brick, rear wing with four entries and a window on the north elevation, and one covered entry with three windows on the south elevation, there is both an end chimney and a ridge chimney. (continued on page 3 of 4 of this form)


30. SUPPORT RESOURCES:

SITE PLAN KEY	FUNCTION	CONSTRUCTION DATE	METHOD/MATERIAL
A	01-A	6: 1850-1874	B0 / Brick
001 B	19 (unknown)	6: 1850-1874	B0 / Brick
002 C	19 (unknown)	6: 1850-1874	B0 / Brick
003 D	19-M	A: 2001-Present	B0 / Brick

31. SITE PLAN (Complete if #27 was answered or if you are using sub-numbers):



32. MAP (Scan or attach copy of map showing exact location of resources):



COUNTY _ Gallatin

RESOURCE # _GA16

GROUP # _____

☒ IDENTIFICATION _____ INTENSIVE

CATEGORY #'s 28

PAGE 3 OF 4 PAGES


KENTUCKY INDIVIDUAL BUILDING

CONTINUATION SHEET (KHC 2014-1)

Architectural Description Continued: The doors match the rear door of the central block with a three light transom above. The main entry has two light transom and two light sidelights. There are three ancillary structures on the property. To the north of the house is a common bond brick octagonal building with a pyramidal, standing seam metal roof (replacement), a sliding window on the southwest elevation, and a doorway on the southeast elevation. To the east is a double-pen, common bond brick, standing seam metal (replacement), gabled roof building with replacement windows. And to the southeast a new brick garage structure. All the windows and roofing has been replaced in the historic buildings on the property.



GA16-House_da_02




GA16-House_da_03




GA16-House_da_04



GA16-House_da_05



GA16-House_da_06



GA16-House_da_07



GA16- outbuilding C_da_08



GA16-Outbuilding C_da_09

COUNTY Gallatin

RESOURCE # GA16

GROUP # _____

☒ IDENTIFICATION _____ INTENSIVE

CATEGORY #'s 28

PAGE 4 OF 4 PAGES

KENTUCKY INDIVIDUAL BUILDING

CONTINUATION SHEET (KHC 2014-1)



GA16-Outbuilding C_da_10




GA16-Outbuilding D_da_11




GA16-Outbuilding B_da_12



GA16-Outbuilding B_da_13



GA16-Outbuilding B_da_14



GA16-House_da_15



GA16-House_da_16

KENTUCKY HISTORIC RESOURCES

COUNTY: Gallatin
RESOURCE # GA-16
RELATED GROUP #
EVALUATION D
SHPO EVALUATION _____
DESTROYED _____

1. NAME OF RESOURCE (how determined): 0/
Gex House

19. FOUNDATION:

TYPE MATERIAL
O/Unknown O/Unknown

2. ADDRESS/LOCATION:

N. side US 42

20. PRIMARY WALL MATERIAL:

E/ Brick

3. UTM REFERENCE:

Quad. Name: Vevay North
Date: 1993 Zone: 16 Accuracy: A
Easting: 673740
Northing: 4292480

21. ROOF CONFIGURATION/COVERING:

CONFIGURATION COVERING
1/ Hip 5/ Asphalt

4. OWNER/ADDRESS:

22. CONDITION: G : Good

23. MODIFICATION: 1: Little alteration

24. NEGATIVE FILE #: 02/02/6-7

5. FIELD RECORDER/AFFILIATION:

H. Powell and Co., Inc.

6. DATE RECORDED: November 2002

7. SPONSOR: KYTC Item No. 6-8002

8. INITIATION: 3 Compliance

9. OTHER DOCUMENTATION/RECOGNITION:

X Survey HABS/HAER
KY Landmark Local Landmark
NR NHL

Other: Site 42
Report Reference "A Cultural Resource Survey of US 42 from
Carrollton to Markland Dam in Carroll and Gallatin Cos., Ky."
2003

10. ORIGINAL PRIMARY FUNCTION: 01A

Single dwelling

11. CURRENT PRIMARY FUNCTION: 99V

Vacant

12. CONSTRUCTION DATE: 6/ c. 1857

13. DATE OF MAJOR MODIFICATIONS:

14. CONSTRUCTION METHOD/MATERIAL:

B/O Brick

15. DIMENSIONS:

Height 2 Width 5B Depth DP

16. PLAN:


H/ Central passage, double pile

17. STYLISTIC INFLUENCE:


3/Mid 19th Century/ 1/ Greek Revival

18. STYLE DEVELOPMENT:

P/ first / second / third



COMMENTS/HISTORICAL INFORMATION:



US 42, CARROLLTON TO MARKLAND DAM, CARROLL AND GALLATIN
COUNTIES, 2003

KENTUCKY HISTORIC RESOURCES INVENTORY

Site No. GA-16

1. Historic Name(s) Original Owner		22. ADD/County GALLATIN 039	
2. Present Name		23. U.S.G.S. Quadrant (15'/75') Vevay NORTH 103	
3. Location N side US 42, 2m W of CARROLL Co. LINE		24. UTM Reference 116 6.73780 42.92500	
4. Owner's Name Mrs. Sams Scott		25. Coordinate Accuracy	
5. Owner's Address Highway 42, 2m W CARROLL Co. LINE		26. Prehistoric Site Historic Site Building	
6. Open to Public Yes No		27. National Register District Name:	
7. Visible from road Yes No		28. Significance Evaluation MEETS NR CRITERIA D	
9. Local Contact/Organization		29. Status National Landmark National Register Landmark Certificate Kentucky Survey Local Landmark HABS/HAER	
10. Site Plan with North Arrow		30. Historic Theme Primary ARCHITECTURE C Secondary Other	
11. Architect		31. Endangered Yes No	
12. Builder		32. Preservation Project Status	
13. Date 1857 A. H B.		Actual Cost in \$1,000s	
14. Style A. GREEK C B. ITALIAN E		33. ATTACH PHOTO	
15. Original Use DWELLING A		Roll No. Picture No. Direction	
16. Present use SAME		34. Prepared by: JCH & RMB	
17. Condition EXCELLENT A		35. Organization KHC	
18. Description LATE GREEK REV., ITALIAN DETAILS. COMMON BOND, STONE CORNICE HEADS OVER WINDOWS. STONE SILLS, STONE WATER TABLE. RECESSED AND PANELED ENTRY WITH SIDE LIGHTS AND TRANSOM. BRACKETED PORTICO WITH PANELED PIERS. WOODEN CAPTAINS WALK. OCTAGONAL OUTBUILDING WITH PYRAMIDAL ROOF. GABLE (Continue on Back) 19. History ROOF OUTBUILDING W/ BOX CORNICE, WITH WIDE WOOD LINTELS		36. Date SUMMER 1981	
20. Significance		37. Revision Dates 38. Staff Review	
21. Source of Information APPROX. B.L.T. 1857 GEX FAMILY MAY HAVE BUILT IT - CHECK W/ DIXIE FROMAN - USED TO BE PART OF FROMAN FARM			

